

MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY BREATH ALCOHOL PROGRAM

DATAMASTER MAINTENANCE REPORT

REPORT #6

Complete this report at the time of the re Complete this report whenever the instru Retain the original and send a copy with	ument is serviced or repaired	and whenever it is p	blaced into serv	days). ice.	
DATAMASTER SN NAME OF AGEN			DATE OF INSPECTIO		8,2013
LOCATION OF INSTRUMENT (STREET AND CITY)	B Tublie SAPE TY	DEF)	TIME OF INSPECTIO	ON ON	
300 NORTH COAL MG	exico Mo			151	
CHECKLIST: Place a mark in the box by where determined.) Unmarked items mu	each item if found to be satisf		ı within establish	ned limits. (Write	e in observed values
DIAGNOSTIC CHECK (PRINTOUT		DATE AND TIME ((from printout)	10/08/13	15:13
COMPUTER		DETECTOR			
□PROGRAM		FILTERS			
THEATERS SAMPLE CHAMBER	<u>49°</u> ∘c	QUARTZ STAP	NDARD		
9 FLOW DETECTOR	,	L CALIBRATION			
PUMP HIGH SPEED		PRINTER			
INDICATOR LIGHTS					
SIMULATOR SOLUTION SUPPLIES	REPCo Marketing	Fnc_LOT#	2002	_ EXP. DATE _	08/29/2014
SIMULATOR TEMP (34°C ± 0.2°C)	34.0° c si	MULATOR SN <u>S.</u>	2669	_ EXP. DATE 4	3/20/2014
CALIBRATION CHECK - (ONLY ON	IE STANDARD IS TO BE US	ED PER MAINTEN	ANCE REPORT	T)	
Run three tests using a standard solution. All three tests must be within ±5% of the standard value and must have a spread of .005 or less. Mark the box corresponding to the standard solution being used. (PRINTOUT ATTACHED)					
0.100% STANDARD - MUST RE. 0.080% STANDARD - MUST RE. 0.040% STANDARD - MUST RE.	AD BETWEEN 0.076% AND	0.084% INCLUSIVE	Ξ		
TEST 1 . 100	TEST 2 ● • ((TEST 3 🖝	.100	
PERFORM R.F.I. TEST (PRINTOUT	ATTACHED)				·
INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT: (DO NOT INCLUDE SELF-ADMINISTERED TESTS)					
REFUSALS (004) &	(.0509)	(.1014)	(.1519)	Ø 0'	/ER .19 📐
LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION (USE OTHER SIDE IF NECESSARY).	OR MODIFICATION THAT WAS MADE TO	O RESTORE THE INSTRUM	ENT TO OPERATE SAT	ISFACTORILY AND W	ITHIN ESTABLISHED LIMITS
(USE OTHER SIDE II ALCESSAIT).					
INSPECTING OFFICER		and the second s	The Free to	an Chairman an Airean Tagairtí	
SIGNATURE		PRINT FULL NA	AME PIEM	NY D.5	m. Tu
TYPE II PERMIT NUMBER/EXPIRATION DATE		TELEPHONE N			
09/28/2014	220326		573-5	81-2100	
RETURN COMPLETED REPORT TO THE:	Breath Alcohol Program, M 2875 James Blvd. Poplar Bluff, MO 63901	O Department of H	ealth and Senio	r Services, Sou	theast District Office



MO 580-0771 (7-88)

PERMIT TYPEII



PENNY D SMITH

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986. Date 09/28/2012 Director of State Public Health Laboratory Expires 09/28/2014 Director, Department of Health Lab. 4 (R7-88)

CERTIFICATE OF ANALYSIS

MANUFACTURER AND SUPPLIER: RepCo Marketing, Inc. LOT NUMBER: 12002

EXPIRATION DATE: August 29, 2014 at 11:59 p.m.

RepCo Marketing, Inc. certifies the following:

RepCo Marketing, Inc. manufactured, tested and supplied Lot Number 12002 of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed by an independent laboratory utilizing a gas chromatograph and found to contain ______ gms/dl +/-.003 gms/dl wt/vol ethanol (95% Confidence).

The alcohol and distilled water used in the solution were found to be free of any interferring substance.

This solution will produce a vapor alcohol value of <u>.100</u> +/-3% gms/210L Breath when heated to 34 Degrees Celsius +/-0.2 Degrees Celsius in a simulator (95% Confidence).

The date of manufacture for this lot number is <u>August 30, 2012</u>

The expiration date for this lot number is <u>August 29, 2014</u> at 11:59 p.m.

This document is a true representation of the original Certificate of Analysis.

Cecil B. Garner, President RepCo Marketing, Inc.

Form RM 02

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

STATE OF MISSOURI
MEXICO DEPARTMENT OF PUBLIC SAFETY

BAC DATAMASTER SERIAL NUMBER 950068 10/08/13 15:13

--- DIAGNOSTIC CHECK ---

COMPUTER:

OKAY

PROGRAM (84-87-2889):

OKAY

HEATERS

SAMPLE CHAMBER:

49c

FLOW DETECTOR:

OKAY

PUMP

HIGH SPEED:

OKAY

DETECTOR:

OKAY

FILTERS:

OKAY

QUARTZ STAMDARDS

OKHY

CALIBRATION:

OKAY

PRINTER TEST

!"#\$%%'()*+,-./0123456789:;<=>?eABCDEF6 HIJKLMMOPQRSTUVWXYZ[\]^_'abcdef9hijklmno parstuvwxyz{|}>÷

Operator Signature

2208-02

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

STATE OF MISSOURI MEXICO DEPARTMENT OF PUBLIC SAFETY

BAC DATAMASTER SERIAL NUMBER 950068 10/08/13

TESTING OFFICER:
SMITH/P
OFFICER I.D.: 09
PERMIT NUMBER: 220326
EXPIRATION DATE: 09/28/14
MISCELLANEOUS DATA:

--- SUPERVISOR MODE ---

BLPMC TEST	. 969	15:17
INTERNAL STAMDARD	VERIFIED	15:17
EXTERNAL STAMDARD	.100	15:18
BLANK TEST	. 999	15:18
EXTERNAL STANDARD	. 199	15:19
BLANK TEST	. 999	15:19
EXTERNAL STANDARD	.188	15:20
BLANK TEST	. AAA	15:20

8 = 3 SIS = .1 AVG. = .1

Operator Signature

2208-02

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

STATE OF MISSOURI
MEXICO DEPARTMENT OF PUBLIC SAFETY

BAC DATAMASTER SERIAL MUMBER 950068 10/08/13

--- BREATH AMALYSIS ---

BLANK TEST
INTERNAL STANDARD
RADIO INTERFERENCE

.000 15:25 VERIFIED 15:25

Operator Signature

2208-02